

Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS		
	From corner to secs. 13, 14, 23 and 24. West, on true line, between secs. 14 and 23. Va. 19°E.	
4.50	Top of spur, Course N.	+ 100
40.00	Set sand stone, 16 x 10 x 4, 10 ins. in ground for the $\frac{1}{4}$ sec. corner, from which, A Fir, 16 ins. diam., bears S.40°E., 8 lks. dist. A Fir, 60 ins. diam., bears N.80°W., 65 lks. dist.	
58.00	Top of ridge, Course NW.	+ 150
80.00	Set Fir post, 40 ins. long, 5 ins. diam., 16 ins. in ground, for the corner to secs. 14, 15, 22 and 23, from which, A Fir, 12 ins. diam., bears N.65°E., 32 lks. dist. A Fir, 10 ins. diam., bears S.84°E., 46 lks. dist. A Fir, 16 ins. diam., bears S.22°W., 100 lks. dist. A Fir, 16 ins. diam., bears N.19°W., 75 lks. dist.	
	Land, principally table or bench lands, second rate. Timber, Fir. Underbrush, but little, and considerable fir.	
	North, on true line, between secs. 14 and 15. Va. 19°E.	
6.00	Top of ridge, Course E. and W.	+ 100
27.50	To South bank of Umpqua river. Marked a Willow, 5 ins. diam., for meander post, from which, A Willow, 5 ins. diam., bears S.75°E., 23 lks. dist. A Willow, 5 ins. diam., bears S.72°W., 11 lks. dist.	
	Across river. Base West 279 lks. Angle opposite 27°, distance over 5.46.	
32.96	Right on North bank of the Umpqua. Land, hilly, second rate. Timber, principally burned.	

August 28, 1874.