

Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS		
	From corner to secs. 14, 15, 22 and 23.	
	South, between secs. 22 and 23.	
	Va. 19*E.	
2.75	A creek, 3 lks. wide, Course W.	- 100
11.50	A creek, 3 lks. wide, Course W.	- 100
40.00	Set a Fir post, 46 ins. long, 5 ins. diam., 20 ins. in ground, for $\frac{1}{2}$ sec. corner, from which, A Fir, 10 ins. diam., bears S.64*E., 45 lks. dist. A Fir, 48 ins. diam., bears N.16*W., 52 lks. dist.	
64.50	A spring branch, Course W.	+ 200
80.00	Set a granite stone, 16 x 12 x 6 ins. ^{10 ins.} in ground, for the corner to secs. 22, 23, 26 and 27.	00
	No live timber near. No witness trees.	
	Land, hilly, third rate.	
	Timber, principally burned.	
	No underbrush.	
	Land covered with fern and pea vine. (wild pea.)	
	East, on Random line, between secs. 23 and 26.	
	Va. 19*E.	
40.00	Set temporary $\frac{1}{2}$ sec. corner.	
80.39	Intersect line, 72 lks. South of corner. South, 89*29'W., on true line.	
5.25	A creek, 15 lks. wide, Course N.	
22.00	Top of spur, Course N.	+ 200
26.00	A creek, 2 lks. wide, Course NE.	
40.19	Set sand stone, 18 x 12 x 6, 12 ins. in ground, for the $\frac{1}{2}$ sec. corner, from which, A Fir, 16 ins. diam., bears North, 18 lks. dist.	
	No other tree near South of line.	
72.00	Top of ridge, Course N. and S.	+ 800
80.39	To sec. corner.	
	Land, broken, mountainous, third rate.	
	Timber, poor, principally burned.	
	August 29, 1874.	