

Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS		
	West, on true line, between secs. 15 and 22.	
	Va. 19°E.	
15.00	A creek, 5 lks. wide, Course NW.	- 200
29.00	A creek, 20 lks. wide, Course NE.	- 200
40.00	Set boulder stone, 18 x 8 x 8.9 ins. in ground. Made mound of three other large stones, for $\frac{1}{4}$ sec. corner. No trees near.	
48.00	Enter green timber.	
56.50	Top of spur, Course SE.	+ 200
72.50	Top of round hill.	+ 600
80.00	Set a Maple post, 40 ins. long, 5 ins. diam., for the corner to secs. 15, 16, 21 and 22, from which, A Fir, 30 ins. diam., bears N.30°E., 169 lks. dist. A Fir, 12 ins. diam., bears S.10°E., 83 lks. dist. A Fir, 24 ins. diam., bears S.18°W., 233 lks. dist. A Fir, 60 ins. diam., bears N.10°W., 25 lks. dist.	+ 400
	Land, broken, third rate. Timber, poor and burned, except last $\frac{1}{4}$ , good Fir.	
<hr/>		
	North, on line between secs. 15 and 16.	
	Va. 19°E.	
9.00	A perpendicular precipice, 40 feet high, Course NW. & SE.	
22.00	Enter river bottom, Course E. and W.	
27.40	South bank of river. Set Willow post, 4 feet long, 4 ins. diam. from which, A Willow, 4 ins. diam., bears S.30°E., 17 lks. dist. A Willow, 6 ins. diam., bears S.62°W., 13 lks. dist.	
	Across river base East 2.90 chs. Angle opposite, 23 $\frac{1}{2}$ °. Distance over 5.17 chs.	
32.57	North bank of river. Land, mountainous, second rate. Timber, principally fir, good.	
	August 31, 1874.	