

Exterior and Subdivision Lines of T. 22 S., R. 9 W.

CHAINS

Land, mountainous, second rate.  
 Timber, principally, Fir. Maple, along river.  
 Underbrush, same, but little.

September 2, 1874.

West, on true line, between secs. 17 and 20.

Va. 19\*E.

- 38.00 A Creek, 1 lk. wide, Course NW.
- 40.00 Set Maple post, 40 ins. by 4 ins. diam., for the  $\frac{1}{4}$  sec. corner, from which,
  - A Maple, 10 ins. diam., bears N.88\*E., 10 lks. dist.
  - A Maple, 10 ins. diam., bears S.88\*E., 10 lks. dist.
- 41.50 A creek, 1 lk. wide, Course N.
- 80.00 Set Maple post, 45 ins. long, 5 ins. diam., 20 ins. in ground. Sets in dry ravine, for corner to secs. 17, 18, 19 and 20, from which,
  - A Maple, 14 ins. diam., bears N.40\*E., 40 lks. dist.
  - A Maple, 12 ins. diam., bears S.55\*E., 77 lks. dist.
  - A Fir, 31 ins. diam., bears S.30\*W., 45 lks. dist.
  - A Maple, 16 ins. diam., bears N.25\*W., 33 lks. dist.

- 400

Land, hilly, third rate.  
 Timber, principally Fir, first rate.

North, on true line, between secs. 17 and 18.

Va. 19\*E.

- 5.00 A dry creek, Course NW.
- 15.00 A creek, 2 lks. wide, Course W.
- 34.00 Enter clearing, Course NE. and SW.
- 39.00 A creek, 3 lks. wide, Course SW.
- 40.00 Set a sand stone, 16 x 12 x 6, 8 ins. in ground. Made stone mound, for the  $\frac{1}{4}$  sec. corner. No witness trees.
- 45.00 Leave clearing, Course NE. and SW.