

Meanders of T. 22 S., R. 9 W.

CHAINS

N.21*E.	13.00	McKaha's house
		S.20*W.
North	5.00	
N.9*E.	12.00	Leave clearing.
N.2*E.	13.00	
N.7*W.	10.00	To meander post.

Land, narrow bottom along river, first rate.
 Bottom, from 1 to 5 chs. wide.
 Timber, principally Maple.
 Underbrush, same, vine-Maple and Willow.

In sec. 7.

N.35*W.	8.00	Head of tide water.
N.10*W.	14.00	Rock Island, W. of line old Indian Encampment.
N.13*E.	2.00	Hill close to river.
N.23*E.	6.50	Sand bar, to river.
N.65*E.	4.00	Rocky, to river.
N.74*E.	10.10	To meander post.

Land, second rate. Valley very narrow along river.
 Timber, some good Fir.
 Underbrush, Willow and vine-Maple, very thick.
 Dams in river at island for fishing.
 Indians encamped along river.

Meander of island in sec. 7.

Lower end of island, from Station No. 2, in the meanders through sec. 7, bears N.67*W., base from Station No. 2. N.10*W., 3.00 chs., Angle opposite, 33* (C.S.80*W.) distance from Station No. 2, N.67*W., 5.51 chs., thence,

N.40*W.	1.00
North	6.00
N.17*E.	6.75