

Meanders of T. 22 S., R. 9 W.

CHAINS

East	.50	
S.4*E.	10.25	
S.40*W.	4.10	To place of beginning.

Land, rocky, third rate.
 Indian encampment on island.
 No timber. Willow in places.

September 4, 1874.

In sec. 8.

N.58*E.	1.00	Rocky steep banks.
N.78*E.	2.00	Rocky steep banks.
N.57*E.	21.00	Rapids in river.
N.85*E.	5.00	Narrow bottom.
S.78*E.	7.50	Willows and vine-Maple.
S.55*E.	3.00	Willows and vine-Maple.
S.45*E.	2.50	Willows and vine-Maple.
S.25*E.	5.00	Willows and vine-Maple.
S.12*E.	9.50	Bottom about 3 chs. wide.
S.7*W.	23.00	Hill closes in to river.
S.9*E.	3.59	To meander post.

Land, second rate.
 Timber, Fir, Maple, and Alder.
 Underbrush, same and Willows and vine-Maple.

In sec. 17.

S.9*E.	3.00	Banks high and
South	16.50	hill close river.
S.22*E.	8.50	Banks high and
S.35*E.	15.00	hill close river.
S.58*E.	12.00	Brushy close river.
S.70*E.	15.00	Brushy close river.
East	4.18	To meander post.