

## County Surveyor's Record, Douglas County, Oregon

## Meanders of T. 22 S., R. 9 W.

CHAINS

Land, mountainous, third rate.

Timber, principally, Fir, Maple and Alder.

Underbrush, same as preceeding line.

In Sec. 16.

S.70*E.	13.00	Bottom about 2 or 3 chs. wide.
N.86*E.	28.00	11 chs. and creek 3 lks. wide.
East	38.87	To meander post.

Land, first rate along bottom.

Timber and underbrush, same as last course.

September 5, 1874.

In sec. 15.

East	11.00	
S.74*E.	3.50	Valley about 6 chs. wide.
N.87*E.	40.00	26.00 chs. to ferry.
S.85*E.	24.97	5.00 chs., creek 5 lks. wide. To meander post.

Land, first rate to creek bottom, about 5 to 8 chs. wide.

Timber, principally Fir, Maple and Alder.

Underbrush, same as preceeding line.

In sec. 14.

N.79*E.	18.50	Mountain close to river.
S.87*E.	62.93	To meander post.

Land, third rate.

Timber, same as last line.

Underbrush, same.