

West. Bdy. of T. 22 S., R. 9 W.

CHAINS

A Yew, 16 ins. diam., bears N.54\*W., 36 lks. dist.  
 Land, very broken and rocky, third rate.  
 Timber, principally Fir and Spruce.  
 November 13, 1877.

South, between secs. 25 and 30.

Va. 19\*E.

8.00 Top of ridge, Course E. and W.  
 26.75 A creek, 3 lks. wide, Course SW.  
 40.00 Marked a Fir tree, 8 ins. diam., for the  $\frac{1}{4}$  sec. corner,  
 from which,  
 An Alder, 10 ins. diam., bears S.70\*E., 11 lks. dist.  
 A Fir, 16 ins. diam., bears S.50\*W., 21 lks. dist.  
 80.00 Set a Fir post, 5 ins. diam., on steep, rocky point.  
 Made rock mound, 12 ins. high, for corner to secs.  
 25, 30, 31 and 36, from which,  
 A Fir, 20 ins. diam., bears N.1\*E., 67 lks. dist.  
 A Fir, 10 ins. diam., bears N.40\*W., 24 lks. dist.  
 A Fir, 16 ins. diam., bears S.25\*E., 135 lks. dist. (estimated)  
 A Fir, 16 ins. diam., bears S.35 $\frac{1}{2}$ \*W., 40 lks. dist. (estimated)  
 Land, rolling and mountainous, second rate.  
 Timber, same as previous line.  
 November 14, 1877.

A small stream (camp creek) runs nearly E. and W., about  
 5 chs. South of this corner and although rather broken  
 and mountainous at this point, it is reported as being  
 very level with good timber and soil. The bottom land  
 along this creek is said to be nearly one mile wide.  
 Some twelve or fourteen claims have already been located.  
 This present work is made to include some lands that are  
 only valuable for the timbers growing thereon.