

## County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 22 S., R. 9 W.  
As surveyed by W. H. Byars,  
Contract No. 279, dated March 5, 1878.

## CHAINS

Beginning at the established corner to secs. 25, 30, 31  
and 36, on Township line between Ranges 9 and 10, West,  
and 22 South, I run, South,

Va. 19°E.

- 3.75 Camp creek, 100 lks. wide, Course W.  
10.25 Camp creek, 50 lks. wide, Course NE.  
17.50 Camp creek, 50 lks. wide, Course NW.  
38.40 Camp creek, 75 lks. wide, Course NE.  
40.00 Set Maple post, 40 ins. long, 5 ins. diam., 18 ins. in  
ground, for  $\frac{1}{4}$  sec. corner, from which,  
A Fir, 20 ins. diam., bears S.80°E., 24 lks. dist.  
A Fir, 36 ins. diam., bears S.45°W., 12 lks. dist.  
50.00 Camp creek, 100 lks. wide, Course N.10°W.  
Begin steep ascent.  
77.00 Top of high burned ridge.  
80.00 Set a stone for corner to T. 22 and 23 S., R. 9 and 10 W.,  
stone 6 x 14 x 16. Made stone mound 4 x 2 feet. No  
timber convenient for witness.  
Land, broken, third rate.  
Creek in canyon with very little bottom along its edges.  
Timber, small, principally Fir.

South Bdy. of T. 22 S., R. 9 W.  
Same Deputy and Contract.

East, on South Boundary of sec. 31.

Va. 19°E.

- 3.00 Top of ridge, Course NW. and SE.  
40.00 Set a Hemlock post, 5 ins. diam., 40 ins. long, 20 ins. in  
ground, for the  $\frac{1}{4}$  sec. corner, from which,  
A Fir, 20 ins. diam., bears North, 18 lks. dist.  
A Fir, 24 ins. diam., bears South, 23 lks. dist.