

## South Bdy. of T. 22 S., R. 9 W.

CHAINS

A Fir, 36 ins. diam., bears N.20\*E., 24 lks. dist.  
 A Chinquapin, 12 ins. diam., bears S.70\*E., 40 lks. dist.  
 A Fir, 20 ins. diam., bears S.50\*W., 24 lks. dist.  
 A Fir, 24 ins. diam., bears N.88\*W., 29 lks. dist.

Post sets on top of ridge.

Land, mountainous, third rate.

Timber, Fir, Cedar and Hemlock, second rate.

Subdivisions of T. 22 S., R. 9 W.  
 W. H. Byars, Deputy Surveyor,  
 Contract No. 274, dated Sept. 10, 1877.

Beginning at the established  $\frac{1}{4}$  sec. corner, between secs.  
 19 and 20, T. 22 S., R. 9 W.

Stone and witness trees all standing.

South, on true line, between secs. 19 and 20.

Va. 19\*E.

39.00 A creek, 3 lks. wide, Course E.

40.00 Set a Fir post, 40 ins. long, 5 ins. diam., 18 ins. in  
 ground, for the corner to secs. 19, 20, 29 and 30,  
 from which,

A Fir, 18 ins. diam., bears N.50\*E., 24 lks. dist.

A Fir, 18 ins. diam., bears S.60\*E., 30 lks. dist.

A Fir, 12 ins. diam., bears S.20\*W., 55 lks. dist.

A Fir, 30 ins. diam., bears N.70\*W., 14 lks. dist.

Land, mountainous, third rate.

Timber, principally, Fir.

West, on Random line, between secs. 19 and 30.

Va. 19\*E.

40.00 Set temporary  $\frac{1}{4}$  sec. corner .

87.63 Intersect line, 140 lks. South of corner.

South, 89\*00\*E., on true line.

33.50 A creek, 5 lks. wide, Course NW.