

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 9 W.

CHAINS

A Maple, 8 ins. diam., bears N.22°E., 21 lks. dist.
Marked T. 21 S., R. 9 W., S. 34 B. T.

A Maple, 16 ins. diam., bears S.73°30'E., 42 lks. dist.
Marked T. 22 S., R. 9 W., S. 3 B. T.

A Fir, 24 ins. diam., bears N.88°W., 59 lks. dist.
Marked T. 21 S., R. 9 W., S. 33 B. T.

A Fir, 24 ins. diam., bears S.76°W., 65 lks. dist.
I destroyed the marks on tree S. of line.

Set Hemlock post, 4½ feet long, 4 ins. square, 24 ins. in ground, at the point of intersection for closing corner, to secs. 3 and 4. Marked C. C. on the S. T. 22 S., S. 3, on the E. R. 9 W., S. 4 on the W. faces, with 3 grooves on the E. and W. sides, from which,

A Fir, 16 ins. diam., bears S.24°E., 66 lks. dist.
Marked T. 22 S., R. 9 W., S. 3 B. T.

A Fir, 20 ins. diam., bears S.43°W., 27 lks. dist.
Marked T. 22 S., R. 9 W., S. 4 B. T.

A Fir, 10 ins. diam., bears N.21°30'W., 20 lks. dist.
Marked C. C. T. 22 S., R. 9 W., S. 3-4 B. T.
Land, mountainous, 77.62 chs.
Soil, second and third rate.

Timber, heavy with Fir, Hemlock, Cedar, Alder, Maple,
Madrone and Cherry.

Undergrowth, dense, vine-Maple, rhododendron, Fir,
Hemlock, Salalberry, Arrow wood and Thimbleberry.

Va. 20°E., 7762 chs.

October 17, 1894.

As all evidence of the corner to secs. 8, 9, 16 and 17,
had been destroyed. I re-established it, as follows:
Commenced at the fractional corner to secs. 8 and 9,
which I re-established, as follows: