

Resurvey of the West Bdy. of T. 22 S., R. 8 W.

CHAINS	<p>Pass over spur.</p> <p>59.90 A creek, 3 lks. wide, Course E. Ascend.</p> <p>73.00 Top of ridge, Course E. and W. † 250 Descend.</p> <p>77.93 To a point, 83 lks. west of the corner to Townships 21 and 22 S., Rs. 8 and 9 W., which is a post 2 feet above ground, 4$\frac{1}{2}$ ins. square, firmly set, marked T. 21 S., S. 31 on the NE., R. 8 W., S. 6 on the SE., T. 22 S., S. 1 on the SW. and R. 9 W., S. 36 on the NW., faces, with 6 notches on the N. S. E. and W. edges, from which, A Fir, 8 ins. diam., bears N.64*E., 22 lks. dist. Marked T. 21 S., R. 8 W., S. 31 B. T. A Fir, 24 ins. diam., bears S.25*E., 28 lks. dist. Marked T. 22 S., R. 8 W., S. 6 B. T. A Fir, 20 ins. diam., bears S.15*W., 36 lks. dist. Marked T. 22 S., R. 9 W., S. 1 B. T. A Fir, 6 ins. diam., bears N.78*W., 21 lks. dist. Marked T. 21 S., R. 9 W., S. 36 B. T. Land, mountainous. 77.93 chs. Soil, second rate. Timber, Fir, Hemlock, Cedar, and Maple. Undergrowth, dense, Fir, vine-Maple, Hazel, and Arrow wood. 77.93 chs. Note: the whole length of this line is 77.93 chs.; error in departure, 83 lks.</p>
	October 15, 1894.
	Resurvey of Subdivisions of T. 22 S., R. 9 W. Same Deputy and Contract.
	<p>Commenced at the $\frac{1}{4}$ sec. corner, between secs. 10 and 11, which is a post, 4 ins. square, marked $\frac{1}{4}$ S. on the W. face, from which, A Fir, 50 ins. diam., bears S.68*E., 22 lks. dist. Marked $\frac{1}{4}$ sec. B. T.</p>