

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 9 W.

CHAINS

A Fir, 20 ins. diam., bears N.80*W., 79 lks. dist.

Marks grown over.

Thence, I run,

North, between secs. 10 and 11.

Va. 20*E.

10.00 A creek, 2 lks. wide, Course E. and W.

Pass over spur.

23.00 A creek, 3 lks. wide, Course W.

Ascend.

40.00 After diligent search, I was unable to find any trace of the corner to secs. 2, 3, 10 and 11, I therefore, Set a Hemlock post, 4½ feet long, 5 ins. square, 24 ins. in the ground on steep hillside sloping NE., marked T. 22 S., S. 2 on the NE., R. 9 W., S. 11 on the SE., S. 10 on the SW., and S. 3 on the NW. faces, with 5 notches on the S., and 2 notches on the E. edges, from which,

An Alder, 20 ins. diam., bears N.9*E., 62 lks. dist.

Marked T. 22 S., R. 9 W., S. 2 B. T.

A Maple, 14 ins. diam., bears S.11*30'E., 49 lks. dist.

Marked T. 22 S., R. 9 W., S. 11 B. T.

A Fir, 30 ins. diam., bears S.38*W., 34 lks. dist.

Marked T. 22 S., R. 9 W., S. 10 B. T.

A Maple, 16 ins. diam., bears N.30*30'W., 27 lks. dist.

Marked T. 22 S., R. 9 W., S. 3 B. T.

Land, mountainous. 40.00 chs.

Soil, second rate.

Timber, Fir, Hemlock and Cedar.

Undergrowth, dense, vine-Maple, Hazel and Fir. 40.00 chs.

October 16, 1894.