

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 22 S., R. 9 W.

## CHAINS

- 39.34 To a point 18 lks. North of the  $\frac{1}{4}$  sec. corner, which is a post marked  $\frac{1}{4}$  S. on the N. face, from which,  
A Maple, 24 ins. diam., bears N.55\*E., 13 lks. dist.  
Marked  $\frac{1}{4}$  S. B. T.  
A Fir, 40 ins. diam., bears S.20\*W., 73 lks. dist.  
Marked  $\frac{1}{4}$  S. B. T.  
Continued N.89\*52'E., from the  $\frac{1}{4}$  sec. corner.
- 46.00 A creek, 5 lks. wide, Course SW.
- 81.28 To a point 25 lks. South of the corner to secs. 32 and 33.  
Land, mountainous. 81.28 chs.  
Soil, second rate.  
Timber, Fir, Hemlock, Maple and Alder.  
Undergrowth, dense, vine-Maple, Hazel, Fir and Hemlock.  
81.28 chs.  
October 31, 1894.
- 
- Commenced at the corner to secs. 9, 10, 15 and 16.  
Thence, I run,  
N.89\*29'E., between secs. 10 and 15.  
Va. 20\*E.  
Descend.
- 41.05 The  $\frac{1}{4}$  sec. corner which is a post marked  $\frac{1}{4}$  S. on the N. face, from which,  
A Fir, 14 ins. diam., bears S.65\*E., 18 lks. dist.  
Marked  $\frac{1}{4}$  S. B. T.  
A Fir, 10 ins. diam., bears N.63\*W., 18 lks. dist.  
Marks grown over.  
Practically agreeing with notes supplied me by the U. S. Surveyor General.
- 64.00 Top of ridge sloping South.  
Descend.
- 82.71 The corner to secs. 10, 11, 15 and 14, which is a post 4 ins. square, marked T. 22 S., S. 11 on the NE., R. 9 W., S. 14 on the SE., S. 15 on the SW. and S. 10