

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 9 W.

CHAINS		
	Pass over spur.	
14.05	A creek, 5 lks. wide, Course NE.	
	Pass over spur.	
27.00	A creek, 10 lks. wide, Course North.	
41.18	To a point 11 lks. South of stone, 10 x 10 x 6 ins. above ground, marked $\frac{1}{4}$ S. on the N. face, from which, A Fir, 18 ins. diam., bears N.20*E., 29 lks. dist. Marked $\frac{1}{4}$ S. B. T. The other B. T. destroyed, I marked, A Fir, 6 ins. diam., bears S.7*E., 28 lks. dist. Marked $\frac{1}{4}$ S. B. T. Continued East from the $\frac{1}{4}$ sec. corner.	
45.25	A creek, 3 lks. wide, Course North. Ascend.	
63.00	Top of ridge sloping North. Descend.	+ 250
80.00	A creek, 2 lks. wide, Course SW. Ascend.	- 350
82.27	To a point 23 lks. North of the corner to secs. 15, 16, 21 and 22. Land, mountainous. 82.27 chs. Soil, second rate. Timber, Fir, Hemlock, Cedar, and Maple. Undergrowth, dense, vine-Maple, Hazel, Salalberry and Fern. 82.27 chs. March 29, 1895.	
	Commenced at the corner to secs. 31 and 32. Thence, I run, N.89*39'W., between secs. 30 and 31. Va. 19*30'E.	
3.70	A creek, 5 lks. wide, Course SE.	- 50