

County Surveyor's Record, Douglas County, Oregon

Resurvey of West Bdy. of Sec. 30, T. 22 S., R. 9 W.,
Same Deputy and Contract.

CHAINS

Commenced at the corner to secs. 25, 30, 31 and 36, in
West Bdy. of Township, between secs. 25 and 30.

Thence, I run, North,

Va. 19°30'E.

37.09 To a point 15 lks. East of the $\frac{1}{4}$ sec on the West Bdy,
of sec. 30, which is a Fir, 12 ins. diam., marks
grown over, from which,
An Alder, 14 ins. diam., bears S.70°E., 10 lks. dist.

Marked $\frac{1}{4}$ s. B. T.

A Fir, 18 ins. diam., bears S.50°W., 22 lks. dist.

Marked $\frac{1}{4}$ s. B. T.

Land, mountainous 37.09 chs.

Soil, second rate.

Timber, Fir, Hemlock, Cedar, Alder and Maple.

Undergrowth, dense, vine-Maple, Hazel, Salalberry, Fir,
Hemlock, and Arrow wood. 37.09 chs.

March 30, 1895.

Resurvey of South Bdy. of sec. 36, T. 22 S., R. 9 W.
Same Deputy and Contract.

Commenced at the corner to secs. 1 and 2, T. 23 S.

Thence, I run, East.

Va. 19°30'E.

11.16 Closing corner to secs. 35 and 36.

28.00 A creek, 4 lks. wide, Course South.

Pass over spur.

42.60 The $\frac{1}{4}$ sec. corner on the South Bdy. of sec. 36, which is
a post marked $\frac{1}{4}$ s. on the N. face, from which,
A Fir, 40 ins. diam., bears N.30°W., 25 lks. dist.

Marked $\frac{1}{4}$ s. B. T.

A Cedar, 50 ins. diam., bears South, 43 lks. dist.

Marked $\frac{1}{4}$ s. B. T.