

County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivisions of T. 22 S., R. 9 W.

CHAINS

A Maple, 20 ins. diam., bears N.25*W., 33 lks. dist.
 Marked T. 22 S., R. 9 W., S. 18 B. T.
 Practically agreeing with notes furnished me by the U. S.
 Surveyor General.
 Land, mountainous. 84.13 chs.
 Soil, second rate.
 Timber, Fir, Hemlock and Maple.
 Undergrowth, dense, vine-Maple, Hazel, Fir and Hemlock.
 84.13 chs.

From the corner to secs. 17, 18, 19 and 20.
 Thence, I run,
 N.89*53*W., between secs. 18 and 19.

Va. 20*E.

Ascend.
 8.00 Top of spur sloping NW. + 200
 Descend.
 30.25 A creek, 35 lks. wide, Course N. - 250
 Ascend.
 41.00 To a point 222 lks. South of the $\frac{1}{4}$ sec. corner, which is
 an Alder, 16 ins. diam., marked $\frac{1}{4}$ S. on the North
 side.
 Land, mountainous. 41.00 chs.
 Soil, second rate.
 Timber, Fir, Maple and Alder.
 Undergrowth, dense, vine-Maple, Hazel, Hemlock and Fir.
 41.00 chs.

March 30, 1895.

Commenced at the corner to secs. 8, 9, 16 and 17.
 Thence, I run, West between secs. 8 and 17.

Va. 20*E.

10.50 Entered John Frazer's improvements.