

45722
 County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivisions of T. 22 S., R. 9 W.

CHAINS

run North 349 lks., when I find the flag on the right bank of river East, which gives for distance across river, Nat. Cot. x base or $2.6050 \times 3.49 = 909$ chs. or whole distance from corner to secs. 7, 8, 17 and 18 will therefore be $41.20 + 9.09$ makes

50.29 East, and 349 North, making to the corner to secs. 8, 9, 16 and 17.

75.13 Land, level and low hills.

Soil, first rate.

Timber, Fir, Maple, Alder and Oak.

Undergrowth, Fir, Oak, vine-Maple, and Hazel.

March 30, 1895.

Commenced at the corner to Secs. 16, 17, 20 and 21.
 Thence I run East between Secs. 16 and 21. Var. $19^{\circ}30'E$.

8.10 Creek, 1 lk. wide, course S. 75° W., pass over spur.

14.05 Creek, 5 lks. wide, course NE., pass over spur.

27.00 Creek, 10 lks. wide, course North

41.18 To a point 11 lks. South of Stone 10 x 10 x 6 in. above ground mkd: $\frac{1}{4}$ S. off the N. face, from which

A fir 18 in. diam. bears N. 20° E. 29 lks. dist., Mkd: $\frac{1}{4}$ S B.T.

The other BT destroyed, I marked, a Fir 6 in. diam., bears S. 7° E. 28 lks. dist. marked $\frac{1}{4}$ S B. T.

Continued East from the $\frac{1}{4}$ Section Corner.

45.25 Creek, 3 lks. wide, course North

Ascend

63.00 Top of ridge, sloping North + 250 Descend + 250

80.00 Creek, 2 lks. wide, Course S. W. - 350 Ascend - 350

82.27 To a point 23 lks. North of the corner to Secs. 15, 16, 21 and 22.

Land, mountainous

Soil, second rate

Timber, fir, hemlock, cedar and maple.

Dense undergrowth of vine maple, hazel, salal, berry and fern.

March 29, 1895