

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 22 S., R. 10 W.

CHAINS	Land, broken, mountainous. Timber, destroyed by fire.
	East, on random bet. secs. 24 & 25. Var. 19* East.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.92	Intersect line 54 lks. South of cor. November 20, 1877.
	South 89*37'W. on true line bet. secs. 24 & 25.
6.00	Small pond North of line about 3 chs.
40.46	Set a fir post, 5 ins. diam., for $\frac{1}{4}$ sec. cor. from which A fir, 8 ins. diam., bears North 112 lks. A fir, 16 ins. diam., bears S.15*W. 62 lks.
42.00	Top of ridge, course S.80*E. & S.80*W.
80.92	To sec. cor. This line has extended along near the dividing ridge bet. the Umpqua River and Camp Creek and has been comparatively level. The land is 3rd rate. Timber good on east half but destroyed by fires on west half.
	From this point the meander post on North side of Umpqua River may be seen. I therefore run North, on true line bet. secs. 23 & 24. Var. 19*E.
	Steep descent.
9.25	Creek, 4 lks. wide, course NW.
32.50	Spur, course NW.
40.00	Set fir post, 4 ins. diam., 18 ins. in ground for the $\frac{1}{4}$ sec. cor. from which A fir, 4 ins. diam., bears N.23*E. 14 lks. A fir, 6 ins. diam., bears N.18*W. 27 lks.
55.75	Enter river bottom, course E. & W.