

## County Surveyor's Record, Douglas County, Oregon

17

## Subdivisions of T. 22 S., R. 10 W.

CHAINS	
58.55	<p>Intersect at meander post on S. side of Umpqua River bet. secs. 23 &amp; 24.</p> <p>Post and witness trees standing.</p> <p>From the post</p> <p style="padding-left: 40px;">A maple, 8 ins. diam., bears N.59*E. 25 lks.</p> <p style="padding-left: 40px;">A maple, 8 ins. diam., bears S.22*W. 18 lks.</p> <p>Land, except in river bottom is utterly worthless for cultivation or timber, the latter having all been destroyed by fire.</p> <p style="text-align: right;">November 21, 1877.</p>
<p>Portion of the West Bdy. of T. 22 S., R. 10 W. As surveyed by W. H. Byars, Deputy Surveyor, under Contract No. 279, dated March 5, 1878.</p>	
7.50	<p>Beginning at the meander post on the North side of the Umpqua River on the Township line bet. Tps. 22, S., Rs. 10 and 11 West.</p> <p style="text-align: right;">Var. 19*East.</p> <p>Run North on true line</p> <p>Top of spur.</p>
14.87	Creek, 2 lks. wide, course E.
37.48	<p>Set stone 6x12x18 for cor. to Tps. 21 and 22 S., Rs. 10 and 11 W., from which</p> <p style="padding-left: 40px;">An alder, 14 ins. diam., bears N.48*E. 52 lks.</p> <p style="padding-left: 40px;">A fir, 48 ins. diam., bears S.45*E. 160 lks.</p> <p style="padding-left: 40px;">A cedar, 36 ins. diam., bears S.2*W. 50 lks.</p> <p style="padding-left: 40px;">An alder, 14 ins. diam., bears N.22*W. 71 lks.</p> <p>Land, rocky, mountainous, 3rd rate.</p>
<p>Portion of the North Bdy. of T. 22 S., R. 10 W. Same Deputy and Contract.</p>	
.50	<p>East, on true line along North Bdy. of sec. 6.</p> <p style="text-align: right;">Var. 19*East.</p> <p>Creek, 1 lk. wide, course S.80*E.</p>