

South Boundary of T. 22 S. R. 10 W.

CHAINS	
49.25	<p>A post, 5 ins. sq., firmly set 2 ft. above ground for cor. to secs. 4 & 5 marked S 4 on E., T 23 S R 10 W on S., S 5 on W. with 4 notches on E. & 2 notches on W. faces from which</p> <p style="padding-left: 40px;">An alder, 8 ins. diam., bears S.13°E. 103 lks. dist. marked T 23 S R 10 W S 4 B T.</p> <p style="padding-left: 40px;">An alder, 10 ins. diam., bears S.50°W. 130 lks. dist. marked T 23 S R 10 W S 5 B T.</p>
52.00	Stream, 4 lks. course N.80°W.
74.25	Stream, 6 lks., course S.45°W.
75.50	<p>This sec. cor. to secs 33 & 32, I also fail to find, it evidently having been destroyed by fire. I therefore made diligent search and at</p>
80.00	<p>An alder, 4 ins. diam., on line which I mark for cor. to secs. 33 & 32 marked S 33 on E., T 22 S R 10 W on N., S 32 on W. with four notches on E. & 2 notches on W. faces, from which</p> <p style="padding-left: 40px;">An alder, 4 ins. diam., bears N.75°E. 50 lks. dist. marked T 22 S R 10 W S 33 B T.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears S.35°E. 20 lks. dist. marked T 22 S R 10 W S 34 & 33 B T.</p> <p style="padding-left: 40px;">An alder, 4 ins. diam., bears N.1°W. 17 lks. dist. marked T 22 S R 10 W S 32 B T.</p>
	Land, mountainous, 80.00 chs.
	Soil, 3rd rate.
	Timber, burnt.
	Dense undergrowth of thimbleberry, 80.00 chs.
	July 25, 1894.
	West, on S. bdy. of sec. 32.
	Var. 20°10'E.
3.50	<p>Stream, course SE.</p> <p>Ascend</p>
9.25	<p>A post 4 ins. sq. firmly set 2 ft. above ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on N. face, from which</p>