

South Boundary of T. 22 S., R. 10 W.

CHAINS

marked T 22 S C C R 10 & 11 W S 1 B T.
 A fir, 40 ins. diam., bears N.55*W. 29 lks. dist.
 marked T 22 S C C R 10 & 11^W S 6 B T.
 Land, mountainous, 104.00 chs.
 Soil, 3rd rate.
 Timber, destroyed by fire.
 Dense undergrowth of thimbleberry, vine maple, hazel,
 sallal & salmonberry.
 July 28, 1894.

West Boundary of T. 22 S., R. 10 W.
 Same Deputy and Contract

4.30

Thence I run
 N. on true line on W. bdy. sec. 31.
 Var. 20*E.
 Descend and at
 Intersect the cor. to T. 22 S., Rs. 10 & 11 W. which is
 a post, 4 ins. sq., firmly set 24 ins. above ground
 marked T 22 S S 36 on N., R 10 W S 31 on E., T 23 S
 S S 1 on S. and R 11 W on W. with 6 notches on N. & W.
 faces, from which
 An alder, 6 ins. diam., bears N.85*30'E. 66 lks. dist.
 marked T 22 S R 10 W S 31 B T.
 A burnt fir, 50 ins. diam., bears S.59*W. 60 lks. dist.
 marked T 23 S R 11 W S 1 B T.
 An alder, 10 ins. diam., bears N.41*W. 36 lks. dist.
 marked T 22 S R 11 W S 36 B T.
 Land, mountainous, 4.30 chs.
 Soil, 3rd rate.
 Timber, burnt.
 Undergrowth, thimbleberry.--not dense.
 July 28, 1894.

Exteriors of T. 22 S., R 10 W.
 Same Deputy and Contract