

45  
Exteriors of T. 22 S., R. 10 W.

CHAINS	
	<p>Finding the west boundary of sec. 13 but 78.60 chs. in length, I go to the meander cor. bet. secs. 13 &amp; 18 on the E. bdy. &amp; N. side or right side of the River and run S. along old line E. bdy. sec. 13.</p> <p>Across river base E. 3 chs. from which flag on S. bank of river bears S.17*36'W. distance across to waters edge.</p>
9.07	And at
9.33	<p>Set a post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for meander cor. bet. secs. 13 &amp; 18, marked T 22 S M C on N., R 9 W S 18 on E., R 10 W S 13 on W. faces, from which</p> <p style="padding-left: 40px;">An alder, 6 ins. diam., bears S.66*E. 40 lks. dist. marked T 22 S R 9 W S 18 B T M C.</p> <p style="padding-left: 40px;">A myrtle, 5 ins. diam., bears S.85*W. 125 lks. dist. marked T 22 S R 10 W S 13 M C B T.</p> <p>Across bottom through potato patch.</p>
13.40	Ascend steep declivitous brushy spur.
19.60	Along E. slope.
23.95	<p>At this point, a fir, 30 ins. diam., marked T 22 S R 9 W S 18 B T. bears N.10*E. 76 lks. dist. The marks were made in the bark and badly defaced by decay and all other marks at this cor. had been destroyed by a slide. I therefore remarked this tree &amp; reestablished the cor. as follows</p> <p>Set a sandstone 14x12x8 ins., 10 ins. in the ground for cor. to secs. 13, 24, 18 &amp; 19, marked with 3 notches on N. &amp; S. edges, from which</p> <p style="padding-left: 40px;">Said fir, 30 ins. diam., bears N.10*E. 76 lks. dist. marked T 22 S R 9 W S 18 B T.</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears S.12*E. 66 lks. dist. marked T 22 S R 9 W S 19 B T.</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears S.30*W. 40 lks. dist. marked T 22 S R 10 W S 24 B T.</p> <p style="padding-left: 40px;">A maple, 12 ins. diam., bears N.33*W. 84 lks. dist. marked T 22 S R 10 W S 13 B T.</p>