

County Surveyor's Record, Douglas County, Oregon

Exterior Boundaries of T. 22 S., R. 10 W.

CHAINS

Land, mountainous, 10.95 chs.  
Soil, first rate in river bottoms.  
A few scattering firs on mountain.  
Dense underbrush of tasselwood, vine maple & thimble-  
berry, 10.95 chs.

Aug. 24, 1894.

8 miles 44 chs. 83 lks. of the exterior lines run over  
mountainous land.

6 miles 17 chs. 45 lks. of the lines re-run run over  
mountainous land.

General Description

This township is extremely rough, broken and mountainous &  
rocky.

The timber is mostly destroyed by fire. Some fir remain-  
ing, mostly in the SE. part.

There are a number of settlers along the river.

Subdivisions of T. 22 S., R. 10 W.  
Same Deputy and Contract.

I go to the cor. to secs. 35 & 36 on the S. bdy. which I  
had previously set.

Thence I run

N.0\*1'W. a random line bet. secs. 35 & 36.

Var. 20\*15'E.

40.00 Set temp. 1/4 sec. cor. and

79.80 Intersect at cor. to secs. 25, 26, 35 & 36. This cor.  
being in bad condition, I remark the trees & reestablish  
the cor. as follows:

A fir, 16 ins. diam., for corl to secs. 25 & 26, 35 & 36,  
marked T 22 S S 25 on NE., R 10 W S 36 on SE., S 35 on  
SW., S 25 on NW. faces with 1 notch on S. & E. edges,  
from which