

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 10 W.

CHAINS
 49.54 A stone in place 6x4x2 ft. above ground which I marked with cross (x) at exact cor. point with 4 notches on S. & 5 notches on E. for cor. to secs. 7, 8, 17 & 18, from which

A fir, 8 ins. diam., bears N.89*E. 225 lks. dist. marked T 22 S R 10 W S 8 B T.

A fir, 8 ins. diam., bears S.85*E. 200 lks. dist. marked T 22 S R 10 W S 17 B T.

A fir, 40 ins. diam., bears S.44*W. 10 lks. dist. marked T 22 S R 10 W S 18 B T.

A fir, 4 ins. diam., bears N.26*W. 13 lks. dist. marked T 22 S R 10 W S 7 B T.

Land, mountainous, 49.54 chs.
 Soil, rocky, 3rd & 4th rate.
 Timber destroyed by fire.
 Dense undergrowth of thimbleberry last 25 chs.
 Aug. 7, 1894.

I run
 East, on a random line bet. secs. 8 & 17.
 Var. 20*30'E.

26.90 Intersect meander cor. bet. secs. 16 & 21.
 Thence I run W. a true line bet. secs. 8 & 17.
 Var. 20*30'E.

Ascend steep rocks.

9.00 Spur, course N.30*E. *200

12.00 Stream, 2 lks., course N.30*E.

15.80 Spur, course N.15*E.

26.90 Intersect at cor. (300 ft. above river) to secs. 7, 8, 17 & 18.
 Land, mountainous, 26.90 chs.
 Soil, 3rd rate, clay.
 Timber destroyed by fire.
 Underbrush, thimbleberry first 12 chs. dense.
 Aug. 7, 1894.