

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R 10 W.

CHAINS	<p>An alder, 10 ins. diam., bears S.62*W. 48 lks. dist. marked $\frac{1}{4}$ S B T.</p>	
64.50	<p>Top of ridge, course SE. Along S. slope.</p>	+600
80.00	<p>Set a sandstone 24x20x10 ins., 18 ins. in the ground for cor. to secs. 10 & 11, marked with 2 notches on E. & 4 notches on S. edges, from which</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears N.5*E. 150 lks. dist. marked T 22 S R 10 W S 11 B T.</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears S.84*E. 83 lks. dist. marked T 22 S R 10 W S 10 & 11 B T.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears N.72*W. 190 lks. dist. marked T 22 S R 10 W S 10 B T.</p> <p>Land, mountainous, 80 chs. Soil, 4th rate, rocky. Timber mostly destroyed by fire. Dense undergrowth, thimbleberry & vine maple.</p> <p style="text-align: right;">Aug. 11, 1894.</p>	
	<p>West, on a true line bet. secs. 10 & 15. Var. 20*30'E.</p> <p>Along S. slope.</p>	
7.00	<p>Descend steep.</p>	
26.75	<p>Stream, 15 lks., course S.15*E. Ascend.</p>	+600
39.50	<p>Ridge, course S.15*E.</p>	+600
40.00	<p>Set a post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. on N. face, from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N.42*W. 33 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears S.60*W. 90 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p>Descend S. slope.</p>	
74.50	<p>Spur, course S.</p>	
80.00	<p>Set a post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 9 & 10 marked T 22 S R 10 W on N.,</p>	-100