

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 10 W.

CHAINS	Ascend SE. slope.	
37.00	Canyon, course SE.	
40.30	A fir, 4 ins. diam., which I marked $\frac{1}{4}$ S. on N. side for $\frac{1}{4}$ sec. cor. from which A fir, 6 ins. diam., bears S.2*E. 9 lks. dist. marked $\frac{1}{4}$ S B T. A fir, 8 ins. diam., bears N.75*W. 18 lks. dist. marked $\frac{1}{4}$ S B T.	
59.50	Stream, 2 lks., course SE.	
65.00	Stream, 2 lks., course S.10*E.	
80.60	The cor. to secs. 1, 2, 11 & 12. Land, mountainous, 80.60 chs. Soil, 3rd & 4th rate, clay. Timber destroyed by fire, mostly fir. Dense underbrush, vine maple, hazel, thimbleberry, sallal & high fern.  Aug. 14, 1894.	
	North 0*1'W. on a random line bet. secs. 1 & 2. Var. 20*30'E.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
93.60	Intersect N. bdy. of Tp. 30 lks. E. of cor. to secs. 1 & 2. Thence I run S.0*12'E. on a true line bet. secs. 1 & 2. Var. 20*30'E.	
	Ascend.	
4.25	Divide, course W. Descend.	+150
16.10	Ridge, course SW.	
26.20	Stream, 1 lk., course S.30*W.	-300
27.00	Stream, 3 lks., course W.	
36.85	Stream, 2 lks., course S.80*W.	
45.10	Ridge, course W.	+200