

Subdivisions of T. 22 S., R. 10 W.

CHAINS	<p>North, 0*4'W. on a true line bet. secs. 5 & 6.</p> <p>Along the random line run July 10</p> <p style="text-align: right;">Var. 20*30'E.</p> <p>Ascend SW. slope.</p>	
12.25	Canyon, course S.35*W.	
27.25	Spur, course S.35*W.	+100
32.00	Canyon, course S.35*W.	-100
35.65	<p>A fir, 8 ins. diam., which I marked $\frac{1}{4}$ S. on W. side for $\frac{1}{4}$ sec. cor., from which</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N.34*E. 10 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A fir, 5 ins. diam., bears S.78*W. 4 lks. dist. marked $\frac{1}{4}$ S B T.</p>	
44.00	Spur, course S.45*W.	+200
58.00	Canyon, course S.85*W.	-100
68.25	Ridge, course S.85*W.	+400
88.60	<p>The cor. to secs. 5 & 6 on the N. bdy. of Tp.</p> <p>Land, mountainous, 80.60 chs.</p> <p>Soil, clay & rocks, worthless, 4th rate.</p> <p>Timber, a few scattering firs.</p> <p>Dense undergrowth of tar balm, grease wood, vine maple, hazel, willow, thimble and huckleberry and sallal.</p> <p style="text-align: right;">Aug. 23, 1894.</p>	
<hr/> <p>Finding that the meander cors. along the river were nearly all destroyed, only the one on the S. or left bank of the river on the W. bdy. and the one on the W. or left bank bet. secs. 8 & 17, I proceed to reestablish those destroyed cors. as follows:</p> <p>I go to the established corner to secs. 13, 14, 23 & 24 which is described on page 100 of these notes and run East, along old line descending along S. slope and at</p>		
21.79	<p>A myrtle, 6 ins. diam. on line which I marked M C T 22 S R 10 W on E., S 13 on N. and S 24 on S. sides for meander cor. bet. secs. 13 & 24, from which</p>	