

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 10 W.

CHAINS

marked T 22 S R 10 W M C. on N., S 24 on E., S 23 on W. faces, for meander cor. bet. secs. 23 & 24, from which

A maple, 8 ins. diam., bears S.63°E. 10 lks. dist. marked T 22 S R 10 W S 24 M C B T.

A maple, 6 ins. diam., bears S.25°W. 28 lks. dist. marked T 22 S R 10 W S 23 M C B T.

July 7, 1894.

In running the W. bdy. of sec. 23, I find it too short.

I therefore go to the meander cor. on the S. or left bank of the river bet. secs. 23 & 24 and run

S.0°1'E. on a random line. I find no evidence of old line nor any marks whatever at 19.55. I made diligent search for $\frac{1}{4}$ sec. cor. but failed to find any. Therefore, I set temp. $\frac{1}{4}$ sec. cor. and at

53.50 The cor. to secs. 23, 24, 25 & 26 bears E. 50 lks.

Therefore from the established cor. to secs. 23, 24, 25 & 26, I run a true line N.33°W. and at

.50 Descend.

8.65 Stream, 4 lks., course NW.

-300

29.00 Top of spur, course N.25°W.

+100

33.95 A hemlock, 6 ins. diam., which I mark with $\frac{1}{4}$ S. on W. side for $\frac{1}{4}$ sec. cor., from which

A hemlock, 6 ins. diam., bears N.45°W. 11 lks. dist. marked $\frac{1}{4}$ S B T.

A fir, 6 ins. diam., bears S.30°E. 30 lks. dist. marked $\frac{1}{4}$ S B T.

52.50 Foot of steep rocky hill, enter bottom

53.50 The meander cor. bet. secs. 23 & 24.

Land, mountainous, 51.50 chs.

Soil, 1st rate, 2 chs. 4th rate, 51.50 chs.

Dense undergrowth, vine maple & hazel, 53.50chs.