

Meanders of T. 22 S., R. 10 W.

CHAINS

Through dense brush.

8.00

Opposite bank of island, marked a willow, 6 ins. diam.

with T 22 S R 10 W M C on E., S 6 on N., S 7 on S.

sides for meander cor. bet. secs. 6 & 7, from which

A spruce, 6 ft. diam., bears S:30*E. 75 lks. dist.

marked T 22 S R 10 W S 6 M C B T.

A willow, 8 ins. diam., bears N.30*W. 25 lks. dist.

marked T 22 S R 10 W S 7 M C B T.

Land, level.

Soil, sandy loam, 1st rate.

Dense underbrush & timber, willow, crab apple, salmon-

berry & ninebark, 8.00 chs.

11 chs.

Across E. prong of river, base S.60*E. angle opposite

60*. Distance across 11 chs.

A willow, 5 ins. diam., which I marked T 22 S R 10 W M

C on W., S 5 on N., S 8 on S. sides for meander cor.

bet. secs. 5 & 8, from which

An alder, 8 ins. diam., bears S.80*W. 15 lks. dist.

marked T 22 S R 10 W S 8 M C B T.

A spruce, 20 ins. diam., bears N.35*W. 100 lks. dist.

marked T 22 S R 10 W S 6 B T M C.

A fir, 30 ins. diam., bears N.1*E. 30 lks. dist.

marked T 22 S R 10 W S 5 M C B T.

An alder, 4 ins. diam., bears S.79*E. 20 lks. dist.

marked T 22 S R 10 W S 8 M C B T.

July 10, 1894.

General Description

This township has a limited range of land and soil. The principal part which comprises more than 90 per cent of the township (all except that part lying along the river where there is some level land which is of rich sandy loam) is mountainous and rocky and covered with