

CHAINS

NW Cor. of T.23S. R.10 W.:

Intersect the NW Cor. of T.23S. R.10W., which is a stone 6x8 ins. firmly set and marked with 6 notches on S. and W. edges: from which:

A fir, 10 ins. dia., bears N.50°E., 11 lks. dist., mkd. C C
T 22 S R 10 W BT.

An alder, 8 ins. dia., bears S.21½°E., 50 lks. dist., mkd. C C
T 23 S R 10 W S 6 BT.

An alder, 10 ins. dia., bears S.47°W., 49 lks. dist. mkd. C C
T 23 S R 11 W S 1 BT.

A post marked ¼ S 1 bears West 19 lks. dist.

Sept. 7, 1905

South 1/4 Cor. Sec. 32 T.22-10 :

Intersect N bdy. of T 23 S, R 10 W, 4.94 chs. N.88°41'W. of ¼ sec cor. on S. bdy. sec. 32, T 22 S., R 10 W. Which is a fir post, 4 ins. sq., 24 ins. above ground, firmly set and marked ¼ S on N. face; from which:

A fir, 18 ins. diam. bears N.52°W. 20 lks. dist. mkd. ¼ S BT.

A fir, 18 ins. diam. bears S.60°W. 37 lks. dist. mkd. ¼ S BT.

These marks had about 12 years growth over them. After diligent search I find no trace of cor. as set under Contract No. 292.

Closing Corner for Secs. 5 & 6:

The cor of secs. 5 and 6, as set under Contract No. 292, bears S.88°32'E., 2.69 chs. dist. I obliterate all trace of this cor. and at the point of intersection, I set a sandstone, 14x12x6 ins. in the ground, for C C of sec. 5 and 6, marked C C on S., with 5 grooves on E, and 1 groove on W. face; from which;

A fir, 12 ins. diam., bears S.78°E., 45 lks. dist. mkd. T23S
R10W S 5 BT.

An alder, 12 ins. diam., bears S.45°W. 9 lks. dist. mkd. T23S
R10W S 6 BT.

Sept. 4, 1906