

County Surveyor's Record, Douglas County, Oregon

T. 22.S., R. 11.W.

CHAINS	<u>Course</u>	<u>Chains</u>	
	S.68*E.	30.00	Mountain steep, and rocky.
	S.38*E.	33.30	
			To M. P. bet. secs. 1 and 6 , on the East bdy. of the T. Land, 3rd rate, Banks high and rocky. Some fir timber along side of mountain.
<u>Subdivisions</u>			
			Begin at the established cor. to secs. 3 & 4, N. bdy. Thence, South on true line bet. secs. 3 & 4. Var. 18*45'E.
5.25	Top of spur, course E.		+300
32.50	Enter brushy bottom, course NE. & SW.		-150
37.00	A creek, 10 lks. wide, course NE.		
40.00	Set 1/4 sec. post from which		
	A willow, 5 ins. diam., bears S.40*E. dist. 17 lks.		
	A willow, 5 ins. diam., bears S.45*W. dist. 3 lks.		
48.00	Leave valley, course NE. & SW.		
80.00	Set stone 12x10x7 for the cor. to secs. 3, 4, 9 & 10,		+200
	from which		
	A dead cedar, 12 ins. diam., bears N.30*E. dist. 22 lks.		
	A bluff of rock four feet high, South 3 lks.		
	No other trees near.		
	Land, generally broken, rocky, 3rd rate.		
	Timber, inferior, mostly burned.		
			East, on a true line bet. sec. 3 & 10. Var. 19*E.
7.75	Top of ridge, course N. & S.		
40.00	Set post for 1/4 sec. cor. from which		-300
	A willow, 8 ins. diam., bears N.75*E. dist. 117 lks.		
	A maple, 4 ins. diam., bears S.34*W. dist. 186 lks.		