

Exterior Boundaries of T. 22 S., R. 11 W.

CHAINS	
	Land, mountainous, 80 chs. Soil, 3rd and 4th rate. Heavily timbered with fir, cedar, hemlock, chittim & alder. Dense undergrowth, thimbleberry, vine maple, sallal and salmonberry, 80.00 chs.
	June 4, 1894.
	South, on a true line on E. bdy. of sec. 36. Var. 19*40'E. Descend through timber.
11.55	Cattle trail, course W.
13.00	Stream, 10 lks. wide, course W. about 400 ft. below cor. Ascend abruptly.
26.90	Spur, course NW. about 250 ft. above stream.
30.40	Gulch, course W. about 100 ft. below spur. Ascend.
40.00	A cherry, 4 ins. diam., which I marked $\frac{1}{4}$ S. on W. side for $\frac{1}{4}$ sec. cor., from which A cedar, 24 ins. diam., bears N.4*E. 49 lks. dist. marked $\frac{1}{4}$ S B T. A chittem, 7 ins. diam., bears S.15*W. 6 lks. dist. marked $\frac{1}{4}$ S B T.
41.80	Stream, 1 lk. wide, course NW. Ascend abruptly.
51.65	Top of mountain, course E. & W. about 400 ft. above stream. Descend.
56.90	Top of a ridge, course SE.
64.55	Fir, 20 ins. diam., marked with 2 notches on N. & S. sides.
68.15	Top of a little spur, course W.
70.90	Gulch, course W. about 100 ft. deep.
81.70	Dry creek bed, 7 lks. wide, course S.60*E. about 500 ft. below top of ridge.