

East Boundary of T. 22 S., R. 11 W.

CHAINS

Heavily timbered with young growth fir and alder.
Dense undergrowth of thimbleberry, huckleberry & sallal.
68.56 chains. July 18, 1894.

Exterior Boundary of T. 22 S., R. 11 W.

In subdividing this township, I was unable to find the
cor. to secs. 4, 5, 32 & 33 on the North bdy.

I found the cor. to secs. 3, 4, 33 & 34 which is a post,
4 ins. sq., marked T 21 S S 34 on NE., T 22 S S 3 on
SE., R 11 W S 4 on SW. and S 33 on NW. faces, with 3
notches on E. & W. edges, from which

A willow, 8 ins. diam., bears S.42 $\frac{1}{2}$ *E. 45 lks. dist.
marked T 22 S R 11 W S 3 B T.

A fir, 30 ins. diam., bears N.21*W. 31 lks. dist.
marked T 22 S R 11 W S 33 B T.

The other bearing trees are gone.

From this cor. I run

West, bet. secs. 4 & 33.

Var. 20*15'E.

Over N. slope.

10.50 A brook, 4 lks. wide, course N.
16.75 A brook, 2 lks. wide, course N.
20.10 A brook, 2 lks. wide, course N.
27.50 A brook, 3 lks. wide, course N.
37.90 A brook, 6 lks. wide, course N.
40.00 At this point I make a thorough search for the $\frac{1}{2}$ sec.
cor. which is described as a post with bearing trees
but find no trace of the same.
52.50 Enter marsh, course NE. & SW.
59.00 Leave thick brush and enter tule.
79.30 Slough, 40 lks. wide, course N.
80.00 At this point I again made a thorough search for the
sec. cor. which is described as a stone 16x10x6 ins.
but was unable to find it.