

## Exterior Boundaries of T. 22 S., R. 11 W.

CHAINS

General Description

The greater portion of this township is rough, mountainous and broken.

The timber is mostly burnt, but the ground is covered with a very dense growth of thimbleberry, salmonberry, sallal, vine maple, young growth alder, fir and hemlock, and in the northwestern portion of the township old growth fir, cedar, spruce and alder timber of fair quality.

There is considerable rich bottom land along Schofield and Dean's Creek, which drain the greater portion of the township and flow into the Umpqua River.

The township south, is mountainous, generally but contains some bottom land along Coos River and its tributaries which drain the greater portion

## Subdivisions of T. 22 S., R. 11 W.

As surveyed by William R. Whipple, Deputy Surveyor, Under Contract No. 612, dated April 28, 1893.

After making a thorough search, I am unable to find any of the meander corners in T. 22 S., R. 11 W. bet. the meander cor. to fractional secs. 1 & 6 on the E. bdy. and the  $\frac{1}{2}$  sec. cor. on the N. bdy. of sec. 3.

I run between these points, on the best ground I could find, and found the difference of latitude to be 48.61 chs. and the departure to be 203.75 chs.

I therefore proceed to reestablish the meander cor. to fractional secs. 1 & 2, 2 & 3 and 3 & 34 as follows;

I commence at the meander cor. to fractional secs. 1 & 6 bet. Rgs. 10 & 11 W. on the left bank of the Umpqua River.

At 8 A. M. June 11th the magnetic bearing of the east bdy. of the township is S.20°30'E. and by table on page 55 of the manual the mean declination is 20°24'E.

Dennis Wagoner's house bears N. 85°W. about 6.50 chs. dist.