

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 22 S., R. 11 W.

CHAINS	Soil, 3rd & 4th rate. Heavily timbered with fir, cedar, alder and maple. Dense undergrowth of thimbleberry, huckleberry, sallow and briars, 72.98 chs.
	Aug. 5, 1894.
	I then began at the cor. of secs. 16 & 17. Thence S.0°3'E. bet. secs. 16 & 17. Var. 20°5'E. Ascend abruptly through timber.
4.50	Top of a ridge, course E. & W. about 250 ft. above car. Descend.
14.30	Bottom of a gulch, course W. about 200 ft. below top of ridge. Ascend.
18.50	Top of a spur on W. slope about 275 ft. above last gulch. Descend.
20.00	Bottom of a gulch, course W. about 75 ft. below last spur. Ascend.
26.50	Top of a ridge, course E. & W. about 250 ft. above last gulch. Descend.
40.00	A stone in place, 24x16x16 ins., above ground which I marked with a cross (x) at exact cor. point and $\frac{1}{4}$ on W. face for $\frac{1}{4}$ sec. cor, from which A fir, 36 ins. diam., bears S.80°E. 135 lks. dist. marked $\frac{1}{4}$ S B T. An alder, 4 ins. diam., bears S.49°W. 89 lks. dist. marked $\frac{1}{4}$ S B T.
44.00	A stream, 2 lks. wide, course W. about 350 ft. below top of last ridge. Ascend.