

County Surveyor's Record, Douglas County, Oregon

Retracement of North Bdy. of T. 23 S., R. 11 W.

CHAINS
 51.00 N.89*33'W. on true line on S. bdy. sec. 32.
 To cor. of secs. 5 & 6 which is a stone 14x12x6 ins.
 marked & witnessed as described by the Surveyor General.
 April 3, 1910

Retracement of Portion of East Boundary of T. 22 S.,
 R. 12 W., as surveyed by Charles A. Slang, Deputy Surveyor,
 under Contract No. 793, dated February 17, 1910.

At the $\frac{1}{2}$ sec. cor., on E. bdy. of sec. 25, which is a
 stone, marked and witnessed as described by the Surveyor
 General.
 Thence I run
 North, on E. bdy. of sec. 25, counting distance from
 this $\frac{1}{2}$ sec. cor.
 Over broken country thru heavy timber and dense under-
 growth.
 10.35 Stream, 1 lk. wide, course NW.
 12.69 The closing cor. of secs. 19 and 30, as described by
 Surveyor General.
 13.18 Stream, 1 lk. wide, course NE.
 Ascend along E. slope.
 34.00 Top of mountain, 300 ft. above creek, bears SE, NW.
 Descend N. slope.
 39.58 Intersect the old cor. of secs. 24 and 25, which is a
 post, marked and witnessed as described by the Surveyor
 General, 70 ft. below mountain.
 Land, mountainous.
 Soil, gravelly; 2nd rate.
 Timber, fir, hemlock, cedar, chittem, maple and dogwood.
 Undergrowth, vine maple, huckleberry and sallah.

From the old cor. of secs. 13 and 24, on the E. bdy. of
 the Tp., which is nearly destroyed, the stone missing
 but bearing trees in position, I run