

North Boundary of T. 23 S., R. 12 W., W.M.
 As surveyed by Wm. P. Wright, Deputy Surveyor,
 under Contract No. 341, dated October 4th, 1879.

CHAINS

Commence the survey of the North Bdy. of this Township by starting from the post corner to Secs. 36, 31, 1 and 6, Townships 22 and 23 S., Ranges 11 and 12 West of Willamette Meridian; found post standing and agreeing with the field notes furnished me by the Deputy Surveyor as the new post on the corrected line, viz:

Maple, 20 ins. diam., bears N.67*W., 50 lks. dist.

Maple, 10 ins. diam., bears N.82*E., 40 lks. dist.

Knowing from previous observation that it will be impossible to run the line through the 6 miles on account of large bodies of water and swamp, I run it as a true line.

Survey commenced

February 5th, 1880.

West, on true line on North bound Sec. 1.

Va.19 $\frac{1}{2}$ *E.

Ascend mountain slope E.

35.00 Top of mountain, descend slope W.

40.00 Set Cherry post, 4x4 by 5 feet long in ground for $\frac{1}{2}$ Sec. corner, from which

A Cherry, 12 ins. diam., bears S.2*W., 20 lks. dist.

A Cherry, 6 ins. diam., bears N.57*W., 19 lks. dist.

Ascend mountain slope SE.

67.50 Top of mountain - descend slope W.

80.00 Set Alder post, 5x6 by 5 ft. long, in ground for cor. to Secs. 1, 2, 35 and 36, from which

An Alder, 20 ins. diam., bears N.88*E., 30 lks. dist.

An Alder, 24 ins. diam., bears S.25*W., 90 lks. dist.

An Elder, 5 ins. diam., bears N.25*W., 10 lks. dist.

Nothing to mark in Sec. 1 near.

Mountain, very rough and steep; almost too steep to chain.

Soil, poor, rocky.

No timber standing.

Undergrowth, Thimbleberries and Elk Brush.