

SUBDIVISIONS, T. 22 S., R. 12 W.

CHAINS		
	Secs. 25, 26, 35 and 36.	
	Thence I run	
	N.89°41'W., on true line bet. Secs. 26 and 35.	
	Va.20°15'E.	
	Descending steeply.	
4.00	A canyon, course NW; begin ascent.	-150
8.50	Top of spur, bears NW and SE, begin descent.	+120
14.00	A canyon, course SW; begin ascent.	-100
19.00	Spur, bears SW and NE; begin descent.	+70
32.50	Foot of descent, enter narrow bottom.	-40
34.40	A branch, water standing in holes about 5 lks. wide, course SW.	
	August 6th, 1889.	
35.00	Begin ascent, leaving bottom.	
39.40	Top of rise, descend along W slope of burnt mountain.	+100
40.39	Set a Cedar post, 3 ft. long, 3 ins. sq. 24 ins. in the ground, for $\frac{1}{2}$ Sec. corner marked $\frac{1}{2}$ S on N face, from which A Spruce, 8 ins. diam., bears S.30°W., 40 lks. dist., marked $\frac{1}{2}$ S B T. A Red Fir, 24 ins. diam., bears N.32°W., 6 lks. dist., marked $\frac{1}{2}$ S B T.	
	The line from here follows the S slope of the burnt mountain, which is covered with numerous logs and old large trees lying N and S along the slope, covered by a dense undergrowth of young trees and brush, and is also terribly cut up by canyons, all of which make it impracticable to survey and mark the line. I make therefore an offset South of 10.00 chs., which brings me to the narrow bottom, thence run	
	N.89°41'W., 40.39 chs. and North 10.00 chs.	
80.78	To corner of Secs. 26, 27, 34 and 35.	
	Land, mountainous.	
	Soil, rocky, 3rd rate.	
	Timber, Fir, Alder, Spruce, Chittenwood, Cherry.	