

SUBDIVISIONS, T. 22 S., R. 12 W.

CHAINS

78.90 A gulch, course S; begin ascent. -90

80.80 The corner to Secs. 9, 10, 15 and 16. +50

Land, mountainous.

Soil, rocky with a thin layer of loam on top - 3rd rate.

Timber, fine Fir, Spruce, Cedar and Alder.

Undergrowth, Salmonberry, Salal, Huckleberries and

Vinemaple.

August 9th, 1889.

West, on a random line bet. Secs. 9 and 16.

Va. 20° 25' E.

40.00 Set temp. 1/4 Sec. corner.

81.86 Intersect N and S line 280 lks. North of corner to Secs. 8, 9, 16 and 17, which is a Spruce post, 4 ins. sq. 24 ins. above ground, marked T 22 S S 9 on NE R 12 W S 16 on SE S 17 on SW S 8 on NW faces, from which

A Spruce, 30 ins. diam., bears N. 76° E., 72 lks. dist., marked T 22 S R 12 W S 9 B T.

A Spruce, 5 ins. diam., bears S. 79° E., 38 lks. dist., marked T 22 S R 12 W S 16 B T.

A Spruce, 30 ins. diam., bears S. 73° W., 28 lks. dist., marked T 22 S R 12 W S 17 B T.

A Spruce, 18 ins. diam., bears N. 70° W., 76 lks. dist., marked T 22 S R 12 W S 8 B T.

in accordance with the description given in the field notes furnished me.

Thence I run

N. 88° E on true line bet. Secs. 9 and 16.

Va. 20° 15' E.

Ascend slightly.

1.80 Top of ridge, bears SW and NE; begin descent. +20

9.00 Foot of ridge, enter low bottom, bears NE and SW. -150

12.50 A branch 5 lks. wide, course N.

*N. 7 E PER MICRO fiche NOTES
CORRECTED 10/10/02 J.R.*