

SUBDIVISIONS OF T. 22 S. R. 12 W. W.M.

CHAINS

marked C C T 22 S R 12 W on N. S 34 On E., S 33 on W. faces with 3 notches on E. and W. faces, from which

A Cherry, 5 ins. diam., bears S. $54\frac{1}{2}^{\circ}$ E., 18 lks.

dist., marked T 23 S R 12 W S 4 B T.

A Cherry, 12 ins. diam., bears N. $88\frac{1}{2}^{\circ}$ E., 19 lks.

dist., marked T. 22 S R 12 W S 34 B T.

A Cherry, 4 ins. diam., bears N. 67° W., 18 lks.,

dist., marked T 22 S R 12 W S 33 B T.

At first I was unable to find the cor. to secs. 3 and 4, the country having been burnt over. I therefore began at the $\frac{1}{4}$ sec. cor. on the North boundary of Section 3 T. 23 S R 12 W, which is an Alder post, 5 ins. sq. 24 ins. above ground marked $\frac{1}{4}$ S on N. face, from which

An Alder, 12 ins. diam., bears N. 9° W., 17 lks.

dist., marked $\frac{1}{4}$ S B T.

An Alder, 12 ins. diam., bears S. 72° W., 29 lks.

dist., marked $\frac{1}{4}$ S B T.

in accordance with the field notes furnished by the Surveyor General's office; thence I run

West, along North boundary of Sec. 3.

Va. $20^{\circ}15'E.$

Descend through timber.

5.50	Intersect arm of North Lake, set temp. meander post, No. 1., run base south 1.00 chs., flag set on line, West, on the opposite shore bears N. $80^{\circ}30'W.$, making 5.98 chs. across.	
11.48	West shore of Lake, set temp. meander post No. 2., begin ascent through burnt timber.	
18.00	Top of spur, bears SE and NW., begin slight descent along south slope of ridge.	+120
33.50	A canyon and branch 2 lks. wide, course SE., begin ascent through heavy brush.	-100
39.60	Intersect 80 lks. South of cor. to secs. 3 and 4, T 23 S R. 12 W.	+400