

SUBDIVISIONS OF T. 22 S. R. 12 W. W.M.

CHAINS

66 = 7.12 chs. across.

37.56 A Fir, 18 ins. diam., on West bank of Eel Lake, which I mark as meander cor. to fractional secs. 29 and 32, M C T 22 S on E., R 12 W S 29 on N., S 32 on S. face, from which

A Fir, 36 ins. diam., bears S.27 $\frac{1}{2}$ *., 13 lks.

dist., marked; T 22 S R 12 W S 32 M C B T.

A Fir, 20 ins. diam., bears N.40 $\frac{1}{2}$ *W., 11 lks.

dist., marked T 22 S R 12 W S 29 M C B T.

Begin ascent of ridge.

40.00 Set an Alder post, 3 ft. long, 3 ins. sq. 24 ins. in the ground, marked $\frac{1}{4}$ S on N. face, from which

A Fir, 36 ins. diam., bears N.63 $\frac{1}{2}$ *E., 46 lks.

dist., marked $\frac{1}{4}$ S B T.

A Maple, 18 ins. diam., bears S.27*E., 39 lks.

dist., marked $\frac{1}{4}$ S B T.

Land, mountainous.

Soil, rocky with a thin layer of loam on top - 3rd rate.

Timber, Spruce, Fir, Hemlock, Cedar, Alder, Maple.

Undergrowth, Salmon, Salal and Huckleberries, Vinemaple.

I discontinued survey at this $\frac{1}{4}$ sec. cor. because there was no more cultivable or settled land west of this corner, the only kind to be surveyed under special instructions.

August 31st, 1889.

Meanders of T. 22 S. R. 12 W.
Same Deputy and Contract.

Meanders of the North end of North Lake, in Sec. 34.

Not being able to find the Alder, marked as "Witness Corner" on the East side of the lake, I went to the $\frac{1}{4}$ Sec. cor. on North boundary of Sec. 3 T 23 S R 12 W and run N.89*11W5.50 chs. to bank of Lake where I re-establish the meander post to fractional Sec. 34 by