

NORTH BOUNDARY OF T. 23 S., R. 12 W. W.M.

CHAINS

A Fir, 30 ins. diam., bears S.60*E., 5 lks.

dist., marked T 23 S R 12 W S 6 M C B T.

A Fir, 6 ins. diam., bears N.56*E., 17 lks.

dist., marked T 22 S R 12 W S 31 M C B T.

Ascend, hill slopes SE.

67.60 Top of hill, N and S.

+200

68.80 A Spruce, 45 ins. diam., begin to descend.

78.25 Thomas house bears S.45*W.

83.00 A stream 1 lk. wide runs NW. Thomas house bears
S.57*E., ascend slope NE.

-50

86.00 Descend.

88.60 Intersect Coast Meridian 294 lks. North of corner to
Townships 22 and 23 South, Ranges 12 and 13 W.

I found the old post still standing in fair state of
preservation marked T 22 S R 12 W S 31 on NE, T 23
S S 6 on SE, R 13 W S 1 on SW and S 36 on NW. There
were some notches in the corners but as they were
cut in the outside growth of the wood they had rotted
off until they were scarcely discernible.

The bearing trees are all standing as follows:

A Hemlock, about 10 ins. diam., bears N.41*E.,
10 lks. dist., marked T 22 S R 12 W S 31 B T
on which I destroyed all marks.

A Fir, 25 ins. diam., bears S.22*E., 48 lks.
dist., The marks were all grown over. I chopped
in and found the marks and hewed them off. I also
destroyed the marks on the NE and SE faces of
the post.

A Hemlock, 15 ins. diam., bearing N.6*W., 42 lks.
dist. and

A Fir, 36 ins. diam., bears S.85*W., 11 lks.
dist., are the other bearing trees plainly
showing the ax marks but the letters and figures