

NORTH BOUNDARY OF T. 23 S. R 12 W. W.M.

CHAINS

being grown over I deemed it best to not disturb the trees by chopping in to find the marks.

At my point of intersection I set a Hemlock post, 5 ins. sq. 5 feet long, 2 feet in ground for closing corner to Secs. 31 and 6, marked T 22 S S 31 on North, T 23 S S 6 on South R 12 W C C on East faces, with 6 notches on North, South and East faces, from which

A Hemlock, 12 ins. diam., bears N.22*E., 44 lks. dist., marked T 22 S R 12 W S 31 C C B T.

A Hemlock, 12 ins. diam., bears S.72*W., 19 lks. dist., marked Ts. 22 and 23 S R 12 W B T.

A Fir, 20 ins. diam., bears S.54*E., 17 lks. dist., marked T 22 S R 12 W S 6 C C B T.

Clear Creek 25 lks. wide running SW passes about 40 lks. NW of this corner.

Soil, 1st and 2nd rate.

Timber, Fir, Spruce, Cedar, Hemlock, Maple and Alder.

Undergrowth, Salmonberry, Salal and Whortleberry.

Soundings in West arm of Eel Lake show a depth of 75 feet.

April 4, 1891.

General Description

The land in this fractional township is mountainous.

Secs. 6 and 7, T 23 S R 12 W are mostly covered with a dense growth of Fir, Spruce and Cedar timber. In Sections 18, 19, 30 and 31, T 22 S R 12 W the old timber is mostly killed by fire.

There is some good land along Eel Lake and also around Ten Mile Lake.

There are 7 or 8 settlers in the western part of the township on the unsurveyed portion.

Subdivisions of T. 22 S., R. 12 W. W.M.
As surveyed by Simon B. Cathcart, Deputy Surveyor
under Contract No. 559, dated November 15th, 1890.