

MEANDERS OF T. 22 S. R. 12 W. W.M.

CHAINS

Thence I run with meanders in Section 30

Va. 20\*05'E

<u>Course</u>	<u>Chains</u>	
N.25*W	6.30	to mouth of creek 20 lks. wide from NW.
N.51*W	1.00	
N.43*E	6.70	heavy timber and thick brush.
S.76 $\frac{1}{2}$ *E	10.80	
S.68*E	2.60	
S.10*E	2.00	
East	1.00	
S.60*E	1.02	to meander post on East side of Lake.
S.53*W	6.20	
S.35*W	.75	
S.16*W	4.50	
S.34*E	3.80	
S.13 $\frac{1}{2}$ *W	2.70	
S.33*W	2.60	
S.34 $\frac{1}{2}$ *E	3.70	<i>Re-microfilm corr made 2/16/90 d.h. Re-CORRECTION 2/22/90 V.L.</i>
S.37*W	1.80	
S.17*E	2.50	
S.6*E	3.80	
South	1.00	Stream 1 lk. wide from East.
West	1.50	
S.45*W	2.40	
N.65*W	5.00	To out-let of Lake 25 lks. wide SW.
N.40*W	4.20	
N.3*W	15.00	Scattering Pine timber.
N.10*W	4.71	To place of beginning.

This is a beautiful lake of very clear fresh water.  
Sounding show the water to be from 48 to 51 feet deep.  
Soil, on west, poor and sandy; remainder, good, 2nd rate.

April 11th, 1891.

Meanders of Clear Lake.

I find the Var. to be 20\*12'E at 8 A.M. April 13th, 1891.