

RETRACEMENT OF SUBDIVISIONS T. 22 S. R. 12 N.

CHAINS	
	<p>this old cor. and reestablish at the same point as follows, because the marks were no longer readable on the bearing trees and the post was missing.</p> <p>Set a Hemlock post, 3 ft. long, 10 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ Sec. cor. marked $\frac{1}{4}$ S 14 on W and 13 on E face, from which:</p> <p style="padding-left: 40px;">A Hemlock, 26 ins. diam., bears N.65*E., 13 lks. dist., marked $\frac{1}{4}$ S 13 B T.</p> <p style="padding-left: 40px;">A Fir, 40 ins. diam., bears N.62*W., 35 lks. dist., marked $\frac{1}{4}$ S 14 B T.</p> <p>From this cor. the Sampson Post Office bears West about 35.00 chs. dist.</p> <p>Thence S.0*15'E.</p>
39.45	Creek, 2 lks. wide, course W.
39.50	Ascend N E slope.
47.09	Top of rise, 200 ft. above beginning of ascent. Descend S. slope.
60.13	Wagon Road, bears E and W. 200 ft. below beginning of descent. Leave timber and pass over level bottom meadow.
62.14	The old school house bears E and W on line.
63.98	Schofield River, 35 lks. wide, gentle current over sandy bottom, course SW.
72.84	Leave meadow, bears E and W, and enter heavy timber and dense undergrowth.
78.84	<p>I destroy all trace of the old cor. and reestablish it at the old point as follows:</p> <p>Set a sandstone, 20x15x10 ins. 15 ins. in the ground for cor. of Secs. 13, 14, 23 and 24, marked with 3 notches on S and 1 notch on E edge; from which</p> <p style="padding-left: 40px;">An Alder, 15 ins. diam., bears N.27*E., 31 lks. dist., marked T 22 S R 12 W S 13 B T.</p> <p style="padding-left: 40px;">An Alder, 38 ins. diam., bears S.48*E., 5 lks. dist., marked T 22 S R 12 W S 24 B T.</p> <p style="padding-left: 40px;">An Alder, 26 ins. diam., bears S.45*W., 50 lks. dist., marked T 22 S R 12 W S 23 B T.</p>