

## RESURVEY OF SUBDIVISIONS, T. 22 S. R 12 W.

CHAINS

Myrtle, Willow and Fern.

April 28, 1910.

At the Cor. of Secs. 24 and 25.

Thence I run

S.1°E., on a true line on W. boundary of Sec. 25.

Ascend broken N. slope thru heavy timber and dense undergrowth.

28.36 Ridge, 700 ft. above cor., bears NE, SW.

Thence along E. crest of ridge.

32.36 Intersect the old  $\frac{1}{4}$  Sec. cor. which is a post marked and witness as described by the Surveyor General. I change the cor. for Sec. 26 only. I destroy marks on E. side of post, from which

A Fir, 60 ins. diam., bears N.23°W., 11 lks.

dist., marked  $\frac{1}{4}$  S 26 B T.

A Cedar, 10 ins. diam., bears S.21°W., 26 lks.

dist., marked  $\frac{1}{4}$  S 26 B T.

Thence, S.0°42'W.

39.11 Same ridge, bears SE, NW.

Over SW slope.

40.00 Set a Cedar post, 3 ft. long, 12 ins. sq. 24 ins. in the ground for  $\frac{1}{4}$  Sec. cor. marked  $\frac{1}{4}$  S 25 on E face, from which

An Alder, 15 ins. diam., bears N.74°E., 39 lks.

dist., marked  $\frac{1}{4}$  S 25 B T.

Maple, 24 ins. diam., bears S.52°E., 40 lks.

dist., marked  $\frac{1}{4}$  S 25 B T.

50.00 Rill 1 lk. wide, course SE.

55.12 Creek, 6 lks. wide, course SW.

65.07 Creek, 6 lks. wide, course NW, 300 ft. below ridge.

Ascend NW slope.

73.69 Intersect the point for old cor. of Secs. 26 and 35. I destroy all trace of this old cor. and reestablish at the same point as follows:

Set a Fir post, 3 ft. long, 10 ins. sq. 24 ins. in