

RETRACEMENTS OF SUBDIVISIONS, T. 22 S. R. 12 W.

CHAINS
48.20

Ravine, 150 ft. deep, course S.

62.79

Branch, 2 lks. wide, course S.

73.84

Ravine, 150 ft. deep, course S.

80.90

The cor. of Secs. 11, 12, 13 and 14.

Land, very broken and mountainous.

Soil, sandy loam; 2nd and 3rd rate.

Timber, Fir, Cedar, Hemlock, Chittem, Alder, Maple,
Dogwood and Yew.

Undergrowth, Vinemaple, Salmonberry, Willow, Alders,

~~Fern~~, Salal, Oregon Grape.

April 30, 1910;

Retracement of E. Bdy. of T. 22 S., R. 12 W.

At the $\frac{1}{4}$ Sec. cor. on E. bdy. of Secs. 25, which is a
stone marked and witnessed as described by the
Surveyor General.

Thence I run

North, on E. bdy. of Secs. 25, counting distance from
this $\frac{1}{4}$ Sec. cor.

Over broken country thru heavy timber and dense undergrowth.

10.35

Stream, 1 lk. wide, course NW.

12.69

The closing cor. of Secs. 19 and 30, as described by
Surveyor General.

13.18

Stream, 1 lk. wide, course NE.

Ascend along E. slope.

34.00

Top of mountain, 300 ft. above creek, bears SE, NW.

Descend N. slope.

39.58

Intersect the old cor. of Secs. 24 and 25, which is a
post, marked and witnessed as described by the
Surveyor General, 70 ft. below mountain.

Land, mountainous.

Soil, gravelly - 2nd rate.

Timber, Fir, Hemlock, Cedar, Chittem, Maple and Dogwood.

Undergrowth, Vinemaple, Huckleberry and Salal.

From the old cor. of Secs. 13 and 24, on the E. Bdy. of
the tp., which is nearly destroyed, the stone missing