

5th Standard Parallel South, R. 13 W., Tps. 22 & 23 S.,
as surveyed by Harvey Gordon, Deputy Surveyor, under
Contract No. 69, dated February 2, 1857.

CHAINS	West, on S. bdy of sec. 36.
7.60	Stream 25 lks, wide, course SW.
26.75	Stream 4 lks. wide, course SE.
40.00	Set qr. sec. post, from which A spruce 8 ins. diam., bears S.89 $\frac{3}{4}$ *E., 1180 lks. dist. A spruce 12 ins. diam., bears N.89 $\frac{1}{2}$ *E., 1178 lks. dist.
72.80	On foot of rocky butte N. of line.
80.00	Set post, cor. of secs. 1, 2, 35 and 36, from which A Dwarf Pine 5 ins. diam., bears N.77 $\frac{1}{2}$ *E., 735 lks. dist. No other bearing trees near and not a suitable place for trench. Land, sandy. Soil, 3rd rate. Timber, spruce and fir. Undergrowth, sallal and manzanita.
<hr/>	
	West, on South boundary of sec. 35.
	Var. 19*E.
40.00	Set qr. sec. post Drove charred stake; not a suitable place for trench and mound.
56.00	Shore of the ocean. Set meander post, deposited a quart of pebbles; place not suitable for mound or trench. Land, same as last mile.
<hr/>	
Subdivisions of T. 22 S., R. 13 W., same Deputy and Contract.	
<hr/>	
	North, bet. secs. 35 and 36.
40.00	Set qr. sec. post, drove charred stake; no mound built on account of the sand.