

## County Surveyor's Record, Douglas County, Oregon

- 4 -

## Subdivisions, T. 22 S., R. 13 W.

CHAINS	
8.23	Opposite snag in water.
26.86	West bank of Clear Lake, set meander post
	A spruce, 24 ins. diam., bears N.67*W., 7 lks. dist.
	A live oak, 6 ins. diam., bears South, 16 lks. dist.
40.31	Set qr. sec. post, from which
	A hemlock, 12 ins. diam., bears South, 15 lks. dist.
	A hemlock, 10 ins. diam., bears North, 38 lks. dist.
80.63	To sec. cor.
	Land, hilly.
	Soil, 3rd rate.
	Timber, fir, spruce and hemlock.
	Undergrowth, sallal and whortleberry.
31.75	West, bet. secs. 23 and 26.
	To Pacific Ocean, set meander post, deposited a quart of stones, no mound.
	Land, sandy.
	Soil, 3rd rate.
12.00	North, bet. secs. 23 and 24.
	Hill, begin to ascend.
30.00	To foot of hill.
40.00	Set qr. sec. post, from which
	A pine, 6 ins. diam., bears S.65*E., 69 lks. dist.
	No tree near west of line.
80.00	Set post, cor. of secs. 13, 14, 23 and 24, from which
	A pine, 4 ins. diam., bears N.26 $\frac{3}{4}$ *E., 65 lks. dist.
	A pine, 4 ins. diam., bears N.15*W., 28 lks. dist.
	No other bearing trees near.
	Land, hilly.
	Soil, 3rd rate.